

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch  
690 Walnut Ave.St. 150  
Vallejo, CA 94592-1133  
(707) 649-5453  
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025563**Date Inspected:** 23-Jul-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 1500**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 300**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Mr. Li Yang ZPMC**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** Trial Assembly Yard OBG 13BW**Summary of Items Observed:**

On this date Caltrans OSM Quality Assurance (QA) Inspector Robert A. DeArmond was present during the time noted above and conducted observations relative to the work being performed.

**TRIAL ASSEMBLY YARD****Magnetic Particle Testing (MT)**

This QA inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an MT report for this date. All components were as listed on NWIT notification no. 09798. The member(s) is/are identified as OBG 13BW Rib Stiffener to Vertical Plate. The weld designations reviewed are as follows

VP3010-001-002, 004, 005, VP3010-001-001, 003

This QA Inspector observed the following work in progress:

FCAW welding of fillet weld joint(s) located on lift 13BW, SA3231D Diverter Plate to Deck Plate weld number(s) 085 and 086. Welder is identified as welder no. 445441. The welding variables recorded by ZPMC QC identified as Li Shen appeared to comply with applicable WPS(s) WPS-B-T-2132-ESAB

FCAW welding of fillet weld joint(s) located on lift 13BW, SA3231D Diverter Plate to Deck Plate weld number(s) 081 and 082. Welder is identified as welder no. 045143. The welding variables recorded by ZPMC QC

---


## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

identified as Li Shen appeared to comply with applicable WPS(s) WPS-B-T-2132-ESAB

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.



### Summary of Conversations:

As mentioned above between QA and QC concerning this project

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150000422372, who represents the Office of Structural Materials for your project.

---

**Inspected By:** DeArmond,Robert

Quality Assurance Inspector

---

**Reviewed By:** Riley,Ken

QA Reviewer